August 2020 Vol. 3

Author: PPN

PPN- The Leading Source of Industry News on Polymer Pipes and Plastic Pipe Testing

Keep Up-to-Date During Corona Isolation with PPN

NEWSMAKERS: * ACP Australian Custom Pipes * Borealis * ExcelPlas * Fletcher Building * GF Piping * Ipex * Iplex * PE100 * PP-RC * PP-RCT * SABIC * Vinidex * Wavin * WSAA

Iplex Parent Fletcher Expects Construction Market to Fall by 20pc http://cloud.excelplas.com/s/i1l6VqrPM2gAZjX#pdfviewer

Iplex Parent Fletcher Building Drops Annual Result Bombshell, Flags \$196m Loss (Breaking News)

https://www.nzherald.co.nz/business/news/article.cfm?c_id=3&objectid=12355440

Iplex Parent Fletcher Building Takes Unusual Step of Announcing what its Results will be Eight Days Before the Official Results Announcement (Breaking News)

https://www.interest.co.nz/property/106464/fletcher-building-takes-unusual-step-announcing-what-its-results-will-be-eight-days

Iplex Parent Fletcher Building Expects to Make a Loss of \$196m (Breaking News) https://www.rnz.co.nz/news/business/423228/fletcher-building-expects-to-make-a-loss-of-196m

GF Piping Reports 14% Drop in Sales Due to Pandemic Lockdowns (Breaking News) https://www.georgfischer.com/en/investors/reports-and-presentations/mid-year-report.html

Borealis Q2 Polyethylene Sales, Profits Sag on Inventory Charges, Fire at Sweden Cracker (Breaking News)

https://www.icis.com/explore/resources/news/2020/08/06/10537911/borealis-q2-sales-profits-sag-on-inventory-charges-fire-at-sweden-cracker

SABIC CEO Warns About Demand as Q2 Prices Slumped 27% (Breaking News) http://www.mrcplast.com/news-news_open-374722.html

GF Piping Systems Announced New Pre-insulated Polyethylene Piping System (New Products)

https://www.pmmag.com/articles/103003-gf-piping-systems-pre-insulated-polyethylene-piping-system

VINIDEX PTY LTD Received WSAA Approval for FRIALEN™ PE100 Electrofusion Fittings for Pressure Applications (New Products)

https://www.wsaa.asn.au/appraisal/vinidex-pty-ltd-frialen-pe100-electrofusion-fittings-pressure-applications

Ipex Showcases Encase™ a Double Containment PP Pipe for Acid Waste (New Products)

https://www.ipexna.com/usa/products/industrial/double-containment-systems/encase-acid-waste-polypropylene/

COOL-FIT® PE Plus is the Next Generation Pre-insulated Plastic Piping System from Georg Fischer (New Products)

https://www.youtube.com/watch?v=INRLq0KUqI4

Improving Pump Efficiency With PP-RCT Piping Systems (New Products) https://www.pumpsandsystems.com/pprct

Wavin Publishes Technical Bulletin on New PP-RC and PP-RCT Pipes (New Products) https://www.wavin.com/tr-en/download/105_S006_43363

WA Seeking HDPE Pipe Extruder Operators

http://www.surepeople.com.au/jobs-in-engineering/for-operators---hdpe-extruder-2560

Iplex Seeking Customer Service Representatives in PVC Pipes

https://www.seek.com.au/job/50369454?type=standout

ACP Australian Custom Pipes Pty Ltd Received WSAA Approval for their Polyethylene (PE100) Pressure Pipe (New Products)

https://www.wsaa.asn.au/appraisal/acp-australian-custom-pipes-pty-ltd-polyethylene-pe-pressure-pipe

ExcelPlas Labs Pipe Failure Investigations

ExcelPlas Labs have created a new benchmark in failure analysis of HDPE, PP-R, PB and PEX pipes in addition to PVC & CPVC pipes as well as composite GRP and GRE pipes. When a plastic pipeline fails to perform as intended, our team can determine the root cause of failure (e.g. oxidative failure, chemical failure, creep failure, over-stress failure, fatigue failure, design failure, etc). ExcelPlas are experienced with all plastic piping failure modes and mechanisms including Slow Crack Growth (SCG) Rapid Crack Propagation (RCP), Environmental Stress Crack Resistance (ESCR), Oxidative Stress Cracking (OSC), cyclic fatigue, manufacturing defects, and polymer material problems.

http://www.excelplas.com/

ExcelPlas Strain Hardening Test (SHT) for HDPE Pipes

The SHT in accordance with ISO 18488 is a relatively new, but excellent way to obtain a rapid indication of the Stress Crack Growth (SCG) resistance of your piping material. This tensile test performed at 80°C has become in just a few years the new standard for Batch Release Testing (BRT). And not without reason. The test requires only a very small amount of material, the results are very reliable with a very low inter-laboratory scatter and the results are available within a few days, regardless of the PE grade. The SHT is usually performed on resin material

but it can also be performed on samples taken directly from pipes or sheets. As accredited lab, EXCELPLAS is happy to discuss the possibilities with you, whether it is for BRT, benchmarking, quality control of your (high performing) PE grade or for polymer compliance/ validation. http://www.excelplas.com/

Australian Plastic Pipe Testing Laboratory

ExcelPlas Laboratories provides a comprehensive plastic pipe joint testing service and is equipped with a state of the art laboratory to test a range of polymer materials including polyethylene and polypropylene. ExcelPlas can carry out testing on plastic tube and pipe ranging in wall thickness from 3 mm to 80 mm. ExcelPlas Laboratories provide a comprehensive service to Industrial & commercial companies, environmental consultants, Government bodies and local Authority customers throughout Australia & NZ. All testing is carried and out in accordance with ISO & ASTM methods and is fully accredited to ISO 17025 by NATA.

http://www.excelplas.com/

Australia's Plastic Pipe Testing Laboratory

ExcelPlas Laboratories provides a comprehensive plastic pipe joint testing service and is equipped with a state of the art laboratory to test a range of polymer materials including polyethylene and polypropylene. ExcelPlas can carry out testing on plastic tube and pipe ranging in wall thickness from 20mm to 1200mm. ExcelPlas Laboratories provide a comprehensive service to Industrial & commercial companies, environmental consultants, Government bodies and local Authority customers throughout Australia and Asia. All testing is carried and out in accordance with ASTM, ISO & WIS methods and is fully accredited to ISO 17025 by NATA.

- Butt Fusion Weld Testing
- Weld Testing
- Testing of Electro-fusion Welds
- Tear on saddle ioints
- Crush De-cohesion of Electro-fusion welds
- Polymer & Plastics Identification
- Chemical & Thermal Testing
- Site Audits

http://www.excelplas.com/

ExcelPlas - the Australian Pipes & Fittings Testing Laboratory

Accredited to ISO 17025 by the National Association of Testing Authorities (NATA)

Australia, and is Australia's largest laboratory dedicated for the testing of plastic pipes and fittings to various Standards which include Australian, European and International Standards.

- The staff employed at the laboratory have a combined experience of more than 85 years within the plastics industry specifically with manufacturing, quality control and the research and development of plastic piping systems including HDPE, PEX, PP-R, PVC, U-PVC, M-PVC, O-PVC, ABS, GRP, GRE and PB.
- Services provided include conformance testing, compliance testing, batch release testing, root cause analysis for field failures and non-destructive testing of samples.
- http://www.excelplas.com/

ExcelPlas Lab Specialising in HDPE Pipe Condition Monitoring, Failure Analysis and Testing

In the event of a HDPE buttweld or electrofusion weld failing during initial testing, or in service, we can conduct investigations to assist in identifying the root cause of the failure. This service also extends to the premature failure of the pipe or fitting itself. http://www.excelplas.com/plastic-pipes

ExcelPlas Pipe Testing is a Leader in the Field of Polyethylene (PE) and High-Density Polyethylene (HDPE) Testing

ExcelPlas is accredited with the National Association of Testing Authorities (NATA) for butt weld tests, bend and tensile tests, peel decohesion tests on electro fusion sockets and failure mode determination

http://www.polypipetesting.com.au/butt-fusion-welds/

New UHMWPE Pipe for Tailing Offers Greater Than 4X the Abrasion Resistance of PE100 (Australia wide)

http://slurrypipes.com.au/

ExcelPlas Poly Pipe Weld Inspection Lists Top 7 Causes of Weld Failure:

- Lack of scraping
- Inaccurate scraping
- Contamination from dirt, water, oil or clays
- Lack of Paralell-ness of fusion faces
- Misalignment of surfaces
- Time, temperature and pressure deviations
- Not adhering to cool times

We have extensive experience in inspection of poly pipe welds for assuring welded joint quality. Direct Poly Pipe Inspection ensures that operators are following the proven welding procedure; this reduces the occurrences of operational errors which lead to defects such as inclusions, lack of fusion (LoF), porosity and misalignment.

More information, contact john@excelplas.com

Get Your HDPE Pipe Products or Services Noticed – Advertise in Poly Pipe News (PPN) Australia

https://www.polypipenews.com.au/advertise/

This Newsletter is brought to you by Excelplas Labs, Australia's Largest group of Poly Pipe Testing Labs.

Pipe Poly News (PPN) is now Australia's most current and comprehensive source of news on Polyethylene pipes and Poly Pipe Welding;

Poly Pipe News is now sent to over 4500 Poly Pipe Industry Members every week.

Any news requests should be sent to <u>john@excelplas.com</u>
To subscribe, visit <u>https://www.polypipenews.com.au/subscribe/</u>

2020 Copyright ExcelPlas Labs?